
Vol. 22

# **TECHNICAL COUNSELING FAQ**

This time, we will introduce "tap burring" and "weak spring type tools" from the questions that we have contacted the tool consultation.



### BURRING FOR THREAD FORM






Fig.1 Burring for thread form



As a countermeasure,

- 1. Adjust the forming position of the pre-hole punching die and burring die on the program. If there is a tendency to tilt the burring end-face, it may be resolved by slightly changing the forming position of the pre-hole punching die.
- 2. The pre-hole and burring are process at the same time.

Our standard burring for thread forming tool is


- In case of downward forming, pre-hole one process type.
- In case of upward forming, the type that processes the pre-hole first.

However, we also have a "pre-hole one process type with upward forming".



The die height of upward forming tools such as burring dies is higher than that of normal punching dies, and if the piercing is performed at a station near the forming tool, the workpiece may be damaged. In such cases, a low height burring die is recommended. (Applicable to t1.0 or less)

Fig.2 Comparison between standard burring die and low height burring die



# **TECHNICAL COUNSELING FAQ**

## ABOUT WEAK SPRING TYPE TOOL

- When a sandwich steel plate is processed, a guide mark is attached to the plate and the product is not manufactured. Isn't there anything you can do about it?
- Normally, in piercing, the stronger the plate pressure, the better the shear results. However, when processing a soft material such as a sandwich steel sheet, the press marks on the guide or stripper may stick to the material.

As a countermeasure.


There is a method to weaken the punch spring.


We offer several types of springs.

By selecting an appropriate spring according to the material, it is possible to eliminate the holding mark.

If you can contact us, we will choose the best spring in our company.

Fig.3 Weak spring type tools





You can select suitable springs depending on materials.



NOTICE: Using a weak spring for thick plate processing may cause a strip error. Please use standard spring type tool for thick plate processing. (To prevent stripping mistakes, a stripping force of 10% to 20% of the punching force is required.)

# ADVICE ON ONE POINT

Other causes of guide marks include,

- •The mounting defect of die. (Burr biting into the bottom of the die.)
- •The defect parallelism of the guide and die end-faces.
  (A failure in mounting a tool of setting during re-grinding)
- •A die (upward tooling die, etc.) with a height is mounted on a nearby station. are also considered.

For More information, please contact CONIC tool sales desk.

#### CONIC Co.. Ltd.

10-5 Taiheidai, Shoo-cho, Katsuta-gun, Okayama 709-4321 Japan Email: tools@conic.co.jp

Email: tools@conic.co.jp https://www.conic.co.jp

## **CONIC PRECISION Co., Ltd.**

55/22 Moo 4, Buengkumphroy, Lumlukka, Phatumthani 12150 Thailand TEL: (662) 159-9870 FAX: (662) 159-9872 Email: conic\_thai@conic.co.jp