


8. Bridge



■ Usage

Used for stopper.


Used for radiating heat of an equipment after processing multiple bridges.

■ Shapes Overview


Bridge is formed on the workpiece.

When the flat part of the surface is extremely long, the cross sectional shape may break into M shape.


Examples



It is a hemispherical bridge.



If the left and right side of the shape is punched with another tool before forming a bridge, the cutting edge of the forming tool will maintain its sharpness for a long time.



This bridge has enough width and durability as a stopper.

Request for a quotation is [here](#).