


12. Lance




■ Usage

Used for ventilation and radiating heat.

■ Shapes Overview

The forming tool cuts and draws a workpiece to make an opening for ventilation.

Example



The larger its standing angle is, the more the burden is imposed on the tool, and then problems such as chipping are likely to occur.

Request for a quotation is [here](#).