





HINGE TOOL



OUTLINE OF FORMING



Forming process to make hinge knuckle.
 Hinge is made of two pieces.
 Each piece include one or more interlocking knuckles
 to create a hinge.

Used for a jointed device on which a door, gate, shutter,
 or other attached part turns, swings, or moves.

NOTE

- 1) Three processes are required to produce hinge.
- 2) $\phi D \leq \phi 5$
 $L \leq 15 \text{ mm}$
 If you require another dimension, please contact us.

For More information,
 please contact
 CONIC tool sales desk.

CONIC Co., Ltd.
 10-5 Taiheidai, Shoo-cho, Katsuta-gun,
 Okayama 709-4321 Japan
 Email: tools@conic.co.jp
<https://www.conic.co.jp>

CONIC PRECISION Co., Ltd.
 55/22 Moo 4, Buengkumphroy, Lumlukka,
 Phatumthani 12150 Thailand
 TEL: (662) 159-9870 FAX: (662) 159-9872
 Email: conic_thai@conic.co.jp