

16. Beading



■ Usage

Used for strengthening and nonslip.
Paper discharge part of copying machine.

■ Shapes Overview

The reinforcing part shaped in a bead is formed by nibbling processing.

Example



As the start and end points are formed ambiguously, we recommend the tool for forming both ends.

Request for a quotation is [here](#).